

C.O.C.: G44353

REPORT No. B14-28156

Report To:

StormPal Inc
 4425 Mapleward,
 Thunder Bay ON P7K 1A4 Canada

Attention: Gavin Swift

Caduceon Environmental Laboratories

3201 Marentette Ave. Unit #5
 Windsor ON N8X 4G3
 Tel: 519-966-9541
 Fax: 519-966-9567

DATE RECEIVED: 28-Oct-14

JOB/PROJECT NO.:

DATE REPORTED: 03-Nov-14

P.O. NUMBER:

SAMPLE MATRIX: Surface Water

WATERWORKS NO.

Parameter	Total Suspended Solids				
Units	mg/L				
M.D.L.	3				
Reference Method	SM 2540D				
Date Analyzed/Site	31-Oct-14/O				

Client I.D.	Sample I.D.	Date Collected				
Forest Trail Tank #1	B14-28156-1	28-Oct-14	64			
Forest Trail Tank #2	B14-28156-2	28-Oct-14	52			
Ulster/Front Tank #1	B14-28156-3	28-Oct-14	172			
Ulster/Front Tank #2	B14-28156-4	28-Oct-14	104			
Ulster/Michigan Tank #1	B14-28156-5	28-Oct-14	2580			
Ulster/Michigan Tank #2	B14-28156-6	28-Oct-14	132			



M.D.L. = Method Detection Limit
 Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill

Lorina Merko
 Lab Supervisor