



STORM PAL INC.
ATTN: GAVIN SWIFT
379 QUEEN ST.
THUNDER BAY ON P7B 2K2

Date Received: 16-AUG-11
Report Date: 22-AUG-11 13:59 (MT)
Version: FINAL

Client Phone: 807-345-1234

Certificate of Analysis

Lab Work Order #: L1044783
Project P.O. #: NOT SUBMITTED
Job Reference:
C of C Numbers:
Legal Site Desc:

Tricia Sampson
Account Manager Supervisor

[This report shall not be reproduced except in full without the written authority of the Laboratory.]

ADDRESS: 1081 Barton Street, Thunder Bay, ON P7B 5N3 Canada | Phone: +1 807 623 6463 | Fax: +1 807 623 7598
ALS CANADA LTD Part of the ALS Group A Campbell Brothers Limited Company

ALS ENVIRONMENTAL ANALYTICAL REPORT

Sample ID Description Sampled Date Sampled Time Client ID	L1044783-1 WATER 18-AUG-11 07:00 PRIMARY TREATMENT TANK	L1044783-2 WATER 18-AUG-11 07:00 SECONDARY TREATMENT TANK			
WATER					
Physical Tests Total Suspended Solids (mg/L)	1240	55.4			
<p>95 % Reduction in TSS</p>					



Sample Receipt Confirmation

Report Distribution:

Company Name: STORM PAL INC.
 Contact: GAVIN SWIFT
 Address: 379 QUEEN ST.,
 THUNDER BAY, ON, P7B 2K2
 Phone: 807-345-1234
 Fax: 807-345-0660
 Email: strompal@shaw.ca
 Report Name: CROSSTAB_ALS
 Digital Type: -
 Digital Email: --
 Distribution: Hard Copy: Y Email: N Fax: Y

Invoice Distribution:

Acct Name: STORM PAL INC.
 Contact: ACCT. PAYABLE
 Address: 379 QUEEN ST.,
 THUNDER BAY, ON, P7B 2K2
 Phone: 807-345-1234
 Fax: 807-345-0660
 Invoice Email: --
 Project #: N/A
 Account #: 18854

Client Information:

Job Reference #: Date Sampled: 16-AUG-11
 Project PO #: Date Received: 16-AUG-11
 Legal Site Description: N/A Sampled By: CLIENT
 Quote #: N/A Chain Of Custody: --

Workorder Summary:

Lab Work Order #: L1044783 Account Manager: Tricia Sampson
 Estimated completion date: 25-AUG-11 Estimated sample disposal date: 24-SEP-11
 2 Samples received at ALS in THUNDERBAY

Lab Sample ID	Client Sample ID	Date Sampled	Date Received	Sample Due Date	Priority Flag	Sample Type	Client Job#
L1044783-1	PRIMARY TREATMENT TANK	16-AUG-11 07:00	16-AUG-11 08:15	25-AUG-11		WATER	
L1044783-2	SECONDARY TREATMENT TANK	16-AUG-11 07:00	16-AUG-11 08:15	25-AUG-11		WATER	

Analysis Requested:

Total Suspended Solids	✓	✓
Sample Handling and Disposal Fee	✓	✓

PRIMARY TREATMENT TANK	✓	✓
SECONDARY TREATMENT TANK	✓	✓

Login Comments:

Your samples were at 16.9 C when unpacked at the laboratory.
 This is significantly above the generally recognized optimal temperature range (less than 10C). Please review your packaging and shipping protocols for future submissions and adjust accordingly. For further assistance, please contact the laboratory.

Sample Integrity Observations: No observations were identified for this work order submission.



ALS Group strives to deliver on-time results to our clients at all times. However, there are times when due to capacity issues or other unforeseen circumstances we are unable to meet our expected turnaround times. The information above is related to a recent workorder you have submitted to our laboratory. In the event that you have an inquiry, please refer to the Lab Work Order # when calling your Account Manager.